

| | | | | | | |
|---|-----------------|--|--|---|---|--------------------------------|
| 1. Approving Civil Aviation Authority/Country: FAA/UNITED STATES | | 2. AUTHORIZED RELEASE CERTIFICATE FAA Form 8130-3, AIRWORTHINESS APPROVAL TAG | | | 3. Form Tracking Number: 160654 | |
| 4. Organization Name and Address: | |  850 S. Dooley St. Grapevine, TX 76051 Phone (817) 481-8205 FAA Approved Repair Station UX2R230L | | | 5. Work Order/Contract/ Invoice Number: 4632 | |
| 6. Item: | 7. Description: | 8. Part Number: | 9. Quantity: | 10. Serial Number: | 11. Status/Work: | |
| 1 | AHRU, LCR-100 | 145130-7010 | 1 | 2642 | INSPECTED | |
| 12. Remark: CW MOD 25 UNIT INSPECTED WITH MANUFACTURERS DOCUMENT NO. 145130-0000-844 BY TECH NO 165 ON 18 OCT 2022 Unit complies with pertinent Airworthiness Directives and Service Bulletins. For work details see Work Order #:160654 Certifies that the work specified in Block 11/12 was carried out in accordance with EASA Part 145 and in respect to that work the [product/article] is considered ready for release to service under EASA Part 145 approval no. EASA 145.4656 | | | | | | |
| 13a. Certifies the items identified above were manufactured in conformity to: <input type="checkbox"/> Approved design data and are in a condition for safe operation. <input type="checkbox"/> Non-approved design data specified in Block 12. | | | 14a <input checked="" type="checkbox"/> 14 CFR 43.9 Return to Service. <input checked="" type="checkbox"/> Other regulation specified in Block 12. Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service. | | | |
| 13b. Authorized Signature: | | 13c. Approval/Authorization No.: | | 14b. Authorized Signature: | | 14c. Approval/Certificate No.: |
| | | | |  | | UX2R230L |
| 13d. Name (Typed or Printed): | | 13e. Date (dd/mmm/yyyy): | | 14d. Name (Typed or Printed): | | 14e. Date (dd/mmm/yyyy): |
| | | | | BUNN D. BUTLER | | 18 OCT 2022 |
| USER/INSTALLER RESPONSIBILITIES | | | | | | |
| It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article. Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/articles(s) from the airworthiness authority of the country specified in Block 1. Statements in Blocks 13a and 14a do not constitute installation certification. In all cases, aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown. | | | | | | |



MASCO SERVICE CORPORATION

850 S. Dooley St. Grapevine, TX 76051
PHONE (817) 481-8205 FAX (817) 488-8918
MASCOSERVICE.COM • SALES@MASCOSERVICE.COM
FAA REPAIR STATION NO. UX2R230L • EASA.145.4656

REPAIR REPORT

| | | |
|------------------------------------|---|----------------------------------|
| ID: 6082 | CUSTOMER: WESTCAN AIRCRAFT SALES & SALVAGE | CUSTOMER ORDER: 4632 |
| NOMENCLATURE: AHRU, LCR-100 | | MANUFACTURER: LITEF |
| AIRFRAME P/N: | MFG P/N: 145130-7010 | SERIAL: 2642 |
| MASCO WORK ORDER NO: 160654 | | MODEL: LCR-100 |
| | | WORK PERFORMED: INSPECTED |
| | | TECH 165 |

REASON FOR REMOVAL:
EVAL FOR REPAIR

PRELIMINARY FINDINGS:
BIT SHOWS NO ENTRIES. ET = 1360.5 HOURS.

TEARDOWN FINDINGS:
NO FAILURE CONFIRMED. AHRU OPERATES NORMALLY ON TEST BENCH.

CORRECTIVE ACTION:
INSPECTED & TESTED PER CMM 145130-0000-844, REV B. UNIT PASSES ALL TESTS.

PARTS REPLACED

| Part No. | Qty. | Description | Part No. | Qty. | Description |
|----------|------|-------------|----------|------|-------------|
| | | | | | |

The article identified above was worked and inspected in accordance with all applicable drawings and specification. Pertinent details of this article are on file at this agency under the above referenced work order.

INSPECTOR BB

DATE 10/18/2022

FORM: MSC-TX09

ISSUE DATE:APRIL 29, 2013

9LBS 16x9x10